

From: Ganetis, George ganetis@bnl.gov
Subject: RE: FXI finding
Date: October 19, 2017 at 5:01 PM
To: Ackerman, Andrew ackerman@bnl.gov
Cc: Lee, Wah-Keat wklee@bnl.gov, Adams, Julian jadams9@bnl.gov, Nehring, Thomas C nehring@bnl.gov

GG

Andrew,

As I stated it is a good practice to run the flexible conduit in a different section of tray. We will take care of this during a maintenance period. If Tom want to make this an action item it should only be a post start.

George Ganetis

From: Ackerman, Andrew
Sent: Thursday, October 19, 2017 4:45 PM
To: Ganetis, George
Cc: Lee, Wah-Keat; Adams, Julian
Subject: FXI finding

George,

The note from Nehring on wiring at FXI is below. Please let me know when this is resolved.

Andrew

"On the roof of Hutch A, fire alarm wiring that is run in flexible, non-metallic conduit passes through the high voltage section of tray. A better practice would be to pass through a low voltage section of tray or circumvent the tray."